L Number	Hits	Search Text	DB	Time stamp
1	987	313/49-51.ccls.	USPAT;	2004/06/12 15:17
			US-PGPUB	
2	29	313/49-51.ccls. and (lamp (arc near3 tube)) and cap\$4 and	USPAT;	2004/06/12 15:24
		connect\$3 and (spring resilien\$3 damp\$3)	US-PGPUB	
3	0	313/317,318.\$2,49-51.ccls. and (lamp (arc near3 tube)) and	USPAT;	2004/06/12 15:27
		(socket cap\$4) and (contact\$ connect\$3) and (spring resilien\$3	US-PGPUB	
		damp\$3) and (cas\$3 holder base housing)		
4	0	(313/317,318.\$2,49-51).ccls. and (lamp (arc near3 tube)) and	USPAT;	2004/06/12 15:27
		(socket cap\$4) and (contact\$ connect\$3) and (spring resilien\$3	US-PGPUB	
_		damp\$3) and (cas\$3 holder base housing)		
5	0	(313/317,318.\$2,49-51).ccls.	USPAT;	2004/06/12 15:26
			US-PGPUB	
6	205781	313/(317,318.\$2,49-51).ccls.	USPAT;	2004/06/12 15:26
			US-PGPUB	
7	205781	313/(317,49-51).ccls.	USPAT;	2004/06/12 15:26
			US-PGPUB	
8	1532	313/317,49-51.ccls.	USPAT;	2004/06/12 15:27
			US-PGPUB	
9	3051	313/317,49-51.ccls. 313/318.\$2.ccls.	USPAT;	2004/06/12 15:27
			US-PGPUB	
10	292	(313/317,49-51.ccls. 313/318.\$2.ccls.) and (lamp (arc near3	USPAT;	2004/06/12 15:34
		tube)) and (socket cap\$4) and (contact\$ connect\$3) and (spring	US-PGPUB	
		resilien\$3 damp\$3) and (cas\$3 holder base housing)		
11	23	(313/317,49-51.ccls. 313/318.\$2.ccls.) and (lamp (arc near3	USPAT;	2004/06/12 15:34
		tube)) and ((socket cap\$4) same (contact\$ connect\$3) same	US-PGPUB	
		(spring resilien\$3 damp\$3) same (adapt\$3))		
12	40	(313/317,49-51.ccls. 313/318.\$2.ccls.) and (lamp (arc near3	USPAT;	2004/06/12 15:55
		tube)) and ((socket cap\$4) same (spring resilien\$3 damp\$3) same	US-PGPUB	
	225	(adapt\$3))		
13	225	439/\$.ccls. and (lamp (arc near3 tube)) and ((socket cap\$4) same	USPAT;	2004/06/12 16:04
	454	(spring resilien\$3 damp\$3) same (adapt\$3))	US-PGPUB	2004/05/40 45 05
14	451	439/\$.ccls. and (lamp (arc near3 tube)) and (((socket cap\$4) with	USPAT;	2004/06/12 16:06
		(spring resilien\$3 damp\$3)) same (case casing housing base	US-PGPUB	
15	0	carrier)) 439/775.ccls. and (lamp (arc near3 tube)) and (((socket cap\$4)	LICDAT.	2004/06/12 16:05
	U	with (spring resilien\$3 damp\$3)) same (case casing housing base	USPAT;	2004/06/12 16:05
		carrier))	US-PGPUB	
16	450	439/\$.ccls. and (lamp (arc near3 tube)) and (((socket cap\$4) with	USPAT;	2004/06/12 16:07
10	750	((socket capse) with (spring resilien\$3)) same (case casing housing base carrier))	US-PGPUB	2004/00/12 10:07
17	.293		USPAT;	2004/06/12 16:08
	255	((socket caps+) with (spring resilien\$3) with (contact\$3 connect\$3)) same (case casing	US-PGPUB	2004/00/12 10.06
		housing base carrier))	03-70708	
18	66	, ,	USPAT;	2004/06/12 16:18
	00	resilien\$3) with (contact\$3 connect\$3)) same (case casing	US-PGPUB	2004/00/12 10.16
		housing base carrier))	03-10100	
19 20	5	439/239-244.ccls. and (lamp (arc near3 tube)) and (((cap\$4) with	USPAT;	2004/06/12 16:19
	3	((Caps+) with (spring resilien\$3) with (contact\$3 connect\$3)))	US-PGPUB	2007/00/12 10.19
	283	439/239-244.ccls. and (lamp (arc near3 tube))	USPAT;	2004/06/12 16:25
	203	100/200 2 Fricals, and flamp (are flear) tabe//	US-PGPUB	2007/00/12 10.23
21	127	439/619.ccls. and (lamp (arc near3 tube))	USPAT;	2004/06/12 16:25
	/	issi, sala ma many (are near a tabe))	US-PGPUB	230 1/00/12 10.23